

SPECIFICATION SHEET

REPLACEMENT PARTS FOR GAS ALERT MONITORS

compatible with both Gas Alert® Micro Clip XL & Gas Alert® Max XT II



51563 † ‡



51564 † ‡



51565 † ‡



51566 † ‡



51568 ‡



51569 ‡



51572 ‡



51590 ‡



51608 † ‡



57658 † ‡



51562 †



51561 † ‡



51554 ‡



51553 † ‡



51555 ‡



51560 † ‡



51559 † ‡



51558 ‡




51557 ‡



51556 ‡



51523 ‡



57634 ‡



57633 ‡



57632 ‡

SKU	DESCRIPTION	UOM	1 - 2	3+	XL	XTII	SKU	DESCRIPTION	UOM	1 - 2	3+	XL	XTII
51563	Replacement BW Tech LEL Sensor	ea	\$155.75	\$144.60	†	‡	51554	Demand Flow Regulator	ea	\$453.25	\$433.85	‡	
51564	Replacement BW Tech O2 Sensor	ea	\$213.15	\$198.85	†	‡	51553	34L Calibration Gas	ea	\$227.70	\$216.95	†	‡
51565	Replacement BW Tech H2S Sensor	ea	\$155.80	\$144.60	†	‡	51555	Concussion-proof boot	ea	\$45.40	\$43.40	‡	
51566	Replacement BW Tech CO Sensor	ea	\$155.75	\$144.60	†	‡	51560	Wall outlet power adaptor	ea	\$19.50	\$19.50	†	‡
51568	Quick connect fittings spares for hoses (2 pack)	ea	\$43.40	\$41.30		‡	51559	Vehicle Charger	ea	\$45.40	\$43.40	†	‡
51569	10' Sampling hose with connectors and 3 particulate filters	ea	\$117.85	\$112.00		‡	51558	Particulate pump filter - 5 per kit	ea	\$19.50	\$18.60	‡	
51572	BW Tech Clear Sampling Hose	ea	\$1.00	.95¢		‡	51557	Hydrophobic pump filter - 5 per kit	ea	\$19.50	\$18.60	‡	
51590	Carrying Holster	ea	\$28.85	\$27.30		‡	51556	Auxillary pump filter - 5 per kit	ea	\$45.40	\$43.40	‡	
51608	Stainless steel replacement clip with screw.	ea	\$31.00	\$28.85	†	‡	51523	GA-M Sintered Particulate Filter	ea	\$27.70	\$23.15	‡	
57658	Gas Monitor - IR Connectivity Kit w/ fleet manager software	ea	\$106.60	\$98.40	†	‡	57634	Replacement BW Tech LCD Screen	ea	\$87.20	\$79.95	‡	
51562	Calibration test cap	ea	\$12.95	\$12.45	†		57633	Replacement BW Tech Pump Cover	ea	\$43.15	\$39.80	‡	
51561	Calibration gas regulator	ea	\$207.30	\$198.50	†	‡	57632	Replacement BW Tech Back Cover	ea	\$86.85		‡	

IN-HOUSE GAS MONITOR CALIBRATION & SERVICE



Your life depends on your gas monitor working correctly, so it is important to ensure that it is serviced & calibrated correctly. Our **IN-HOUSE TECHNICIANS** work on BW Technologies and MSA Monitors at our New York facility, & offer:

- ✓ Fast turnaround.
- ✓ Accurate calibration with certificate.
- ✓ Detailed record keeping.
- ✓ Large inventory of spare parts to limit down time.

CALL FOR MORE DETAILS **800.451.5811**

